

FIG. 1




FIG. 2




FIG. 3

COLUMN ROW	1	2	3	4	5
1	$J_{-7}(x_1) \cdot J_{-2}(x_2)$	$J_{-7}(x_1) \cdot J_{-1}(x_2)$	$J_{-7}(x_1) \cdot J_0(x_2)$	$J_{-7}(x_1) \cdot J_1(x_2)$	$J_{-7}(x_1) \cdot J_2(x_2)$
2	$J_{-6}(x_1) \cdot J_{-2}(x_2)$	$J_{-6}(x_1) \cdot J_{-1}(x_2)$	$J_{-6}(x_1) \cdot J_0(x_2)$	$J_{-6}(x_1) \cdot J_1(x_2)$	$J_{-6}(x_1) \cdot J_2(x_2)$
3	$J_{-5}(x_1) \cdot J_{-2}(x_2)$	$J_{-5}(x_1) \cdot J_{-1}(x_2)$	$J_{-5}(x_1) \cdot J_0(x_2)$	$J_{-5}(x_1) \cdot J_1(x_2)$	$J_{-5}(x_1) \cdot J_2(x_2)$
4	$J_{-4}(x_1) \cdot J_{-2}(x_2)$	$J_{-4}(x_1) \cdot J_{-1}(x_2)$	$J_{-4}(x_1) \cdot J_0(x_2)$	$J_{-4}(x_1) \cdot J_1(x_2)$	$J_{-4}(x_1) \cdot J_2(x_2)$
5	$J_{-3}(x_1) \cdot J_{-2}(x_2)$	$J_{-3}(x_1) \cdot J_{-1}(x_2)$	$J_{-3}(x_1) \cdot J_0(x_2)$	$J_{-3}(x_1) \cdot J_1(x_2)$	$J_{-3}(x_1) \cdot J_2(x_2)$
6	$J_{-2}(x_1) \cdot J_{-2}(x_2)$	$J_{-2}(x_1) \cdot J_{-1}(x_2)$	$J_{-2}(x_1) \cdot J_0(x_2)$	$J_{-2}(x_1) \cdot J_1(x_2)$	$J_{-2}(x_1) \cdot J_2(x_2)$
7	$J_{-1}(x_1) \cdot J_{-2}(x_2)$	$J_{-1}(x_1) \cdot J_{-1}(x_2)$	$J_{-1}(x_1) \cdot J_0(x_2)$	$J_{-1}(x_1) \cdot J_1(x_2)$	$J_{-1}(x_1) \cdot J_2(x_2)$
8	$J_0(x_1) \cdot J_{-2}(x_2)$	$J_0(x_1) \cdot J_{-1}(x_2)$	$J_0(x_1) \cdot J_0(x_2)$	$J_0(x_1) \cdot J_1(x_2)$	$J_0(x_1) \cdot J_2(x_2)$
9	$J_1(x_1) \cdot J_{-2}(x_2)$	$J_1(x_1) \cdot J_{-1}(x_2)$	$J_1(x_1) \cdot J_0(x_2)$	$J_1(x_1) \cdot J_1(x_2)$	$J_1(x_1) \cdot J_2(x_2)$
10	$J_2(x_1) \cdot J_{-2}(x_2)$	$J_2(x_1) \cdot J_{-1}(x_2)$	$J_2(x_1) \cdot J_0(x_2)$	$J_2(x_1) \cdot J_1(x_2)$	$J_2(x_1) \cdot J_2(x_2)$
11	$J_3(x_1) \cdot J_{-2}(x_2)$	$J_3(x_1) \cdot J_{-1}(x_2)$	$J_3(x_1) \cdot J_0(x_2)$	$J_3(x_1) \cdot J_1(x_2)$	$J_3(x_1) \cdot J_2(x_2)$
12	$J_4(x_1) \cdot J_{-2}(x_2)$	$J_4(x_1) \cdot J_{-1}(x_2)$	$J_4(x_1) \cdot J_0(x_2)$	$J_4(x_1) \cdot J_1(x_2)$	$J_4(x_1) \cdot J_2(x_2)$
13	$J_5(x_1) \cdot J_{-2}(x_2)$	$J_5(x_1) \cdot J_{-1}(x_2)$	$J_5(x_1) \cdot J_0(x_2)$	$J_5(x_1) \cdot J_1(x_2)$	$J_5(x_1) \cdot J_2(x_2)$
14	$J_6(x_1) \cdot J_{-2}(x_2)$	$J_6(x_1) \cdot J_{-1}(x_2)$	$J_6(x_1) \cdot J_0(x_2)$	$J_6(x_1) \cdot J_1(x_2)$	$J_6(x_1) \cdot J_2(x_2)$
15	$J_7(x_1) \cdot J_{-2}(x_2)$	$J_7(x_1) \cdot J_{-1}(x_2)$	$J_7(x_1) \cdot J_0(x_2)$	$J_7(x_1) \cdot J_1(x_2)$	$J_7(x_1) \cdot J_2(x_2)$

FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9A




FIG. 9B




FIG. 10A




FIG. 10B